




















































ФУРНИТУРА / HARDWARE					ИНСТРУМЕНТЫ / TOOLS
A  28 X	B'  28 X	C  32 X	D  4 X	E  28 X Ø18	 
F  12 X	G  14 X	H  40 X 4x16	I  20 X 6x14	J  2 X	

КОМПЛЕКТУЮЩИЕ / PARTS		
①  4 X	②  8 X	③  8 X
①.1 	④  1950*554	
①.2 		
⑤  1950*554	⑥ 	⑦  3 X 522*423
⑧  938*556	⑨  902*522	⑩  902*522
⑪  902*536	⑫  522*296	⑬  1288*522
⑭  1942*912	⑮  2 X 500*250	⑯  2 X 500*250
⑰  2 X 385*250	⑱  2 X 447*320	⑲  2 X 494*395
⑳  1623*447	㉑  1623*447	












20



21



22

